

# BOBCAT® REPLACEMENT PARTS

[Go Back](#)



## BOBCAT® REPLACEMENT PARTS

ALL PRICES SUBJECT TO CHANGE WITHOUT NOTICE

### BOBCAT® UNIFIED PISTONS

Bobcat ® Part Number	Thunderbird Part Number	Bore	Width	Thru Hole	Price
6661694	Y-1204	2.00	1.25	0.750	\$32.00
6661820	Y-1268	2.25	1.25	1.000	\$37.00
6665013	Y-1023	2.00	2.00	1.000	\$37.00
6665027	Y-1267	2.25	1.00	1.000	\$37.00
6665715	Y-1004	3.00	1.00	0.875	\$45.00
6666286	Y-1211	2.75	1.00	1.125	\$44.00
6669993	Y-1006	3.00	1.00	1.125	\$45.00
6667291	Y-1209	2.50	1.00	1.000	\$37.00
6673791	Y-1210	2.50	1.00	0.875	\$37.00

### BOBCAT® UNIFIED GLANDS

<b>Bobcat ®</b>	<b>Thunderbird</b>				
<b>Part Number</b>	<b>Part Number</b>	<b>Rod</b>	<b>Bore</b>	<b>Length</b>	<b>Price</b>
6536968	6356968 (U)	1.375	2.750	2.00	\$63.21
6800686	6800686 (U)	1.500	2.750	2.750	\$66.72
6538367	6538367UG	1 1/2	3	2.00	\$70.00
7106798	7106798UG	1 1/4	2 1/4	2.15	\$66.72

***(U) Unified Gland Assembly includes: Molded on Wear Band, Double Lip Rod Seal, Rod Wiper, O-Ring***

BOBCAT PART NUMBERS ARE FOR REFERENCE PURPOSES ONLY  
 ALL PRICES SUBJECT TO CHANGE WITHOUT NOTICE

For information or to place an order call 1.304.342.6045 or email [sales@thunderbirdindustries.com](mailto:sales@thunderbirdindustries.com)  
 Effective August 01, 2017